

# Summary of EPA review of Parcel G Trench

Number of TU's	% of Parcel G total
63	100%
<i>Navy reviewed 63 total Trench Units to loo</i>	
20	32%
0	0%
43	68%
<i>EPA reviewed the 43 Trench Units recommi</i>	
1	2%
8	13%
34	54%
<i>Total Navy and EPA recommend for resamp</i>	
54	86%

Trench Unit	EPA score
TU089	0
TU078	1
TU079	1
TU103	1
TU106	1
TU107	1
TU118	1
TU119	1
TU151	1
TU067	2
TU068	2
TU069	2
TU071	2
TU072	2
TU073	2
TU074	2
TU075	2
TU076	2
TU080	2
TU082	2
TU083	2
TU085	2
TU087	2
TU088	2
TU091	2
TU092	2
TU093	2
TU096	2
TU097	2

# 1 Units Draft 10-16-2017

Total trench units in Parcel G
<i>k for signs of potential falsification</i>
Navy recommended confirmation sampling due to signs of potential falsification
Navy recommended reanalysis of archived samples
Navy recommended NFA = No further action due to signs of falsification, but potential further action due to uncertainty
<i>ended for NFA</i>
EPA score 0 = No specific findings of particular concern
EPA Score 1 = Need further review
EPA Score 2 = Need resampling before determination that the record supports ROD requirements met
<i>oling</i>

**83% of total TU's now recommended for resampling and 17% need further evaluation**

Note: TU 66 and TU 70 the Navy recommended for partial re-sampling only. However, both are marked for full resampling due to suspect soil from the fill unit that was used to fill those TUs.

TU098	2
TU099	2
TU100	2
TU101	2
TU102	2
TU102	2
TU104	2
TU108	2
TU111	2
TU115	2
TU116	2
TU117	2
TU121	2
TU124	2
TU204	2

